

Effective Number of Personnel	QMS Base Man-Days	Low Risk (25% Increase)	Medium Risk (50% Increase)	High Risk (75% Increase)
1–5	1.5	2	2.5	3
6–10	2	2.5	3	3.5
11–15	2.5	3	4	4.5
16–25	3	3.5	4.5	5.5
26–45	4	5	6	7
46–65	5	6.5	7.5	8.5
66–85	6	7.5	9	10.5
86–125	7	8.5	10.5	12
126–175	8	10	12	14
176–275	9	11.5	13.5	16
276–425	10	12.5	15	17.5
426–625	11	13.5	16.5	19.5
626–875	12	15	18	21
876–1175	13	16.5	19.5	23
1176–1550	14	17.5	21	24.5
1551–2025	15	19	22.5	26.5
2026–2675	16	20	24	28
2676–3450	17	21.5	25.5	30
3451–4350	18	22.5	27	31.5
4351–5450	19	23.5	28.5	33.5
5451–6800	20	25	30	35